


Phase III - NMFS GALVESTON, TX

Renovation of Buildings 301, 303, 305, 306 & 307



Project Description:

Renovation: Complete Phase III Renovation of Buildings 301, 303, 305, 306, and 307 & Site Work at the NMFS Laboratory located in Galveston, TX. The renovation includes demolition of the existing buildings, ground floor slabs, abatement of asbestos materials. Work also includes replacement of the building's architectural interior finishes, building HVAC systems, plumbing, electrical systems, interior/exterior strip footings and installation of fire protections systems, hydraulic elevators, repair and construction of anew roof, and HVAC Control systems.




Phase III - NMFS GALVESTON, TX

Renovation of Buildings 301,303,305,306 & 307



Deteriorated Condition of Buildings 301, 303, 305, 306 & 307



Phase III - NMFS GALVESTON, TX

Renovation of Buildings 301,303,305,306 & 307



Deteriorated Condition of Buildings 301,303,305,306 & 307